#### Board of Selectmen

MEETING TUESDAYS AT 7 00 P M

**UPPER TOWN HALL** 

1 MAIN STREET

**AYER, MASSACHUSETTS 01432** 

23685

Tel (978) 772-8220 iax (978) 772-3017

Town Administrator (978) 772-8210

September 19, 2008

Surface Transportation Board Attn Ann Newman 395 E Street, S W. Washington, DC 20024

> RE: Additional Copies of Filed Materials

> > Finance Docket No. 35147

Norfolk Southern Railway Company, Pan Am Railways, Inc. et al.

Joint Operating Agreements - Pan Am Southern LLC

#### Dear Ms Newman:

In response to your telephone request enclosed please find ten color copies of the proposed monitoring well locations associated with the Town of Ayer's Spectacle Pond wellfield.

As noted in prior filings, a planned auto-unloading facility would be situated directly atop the Mass Dept. of Environmental Protection designated Zone II aquifer recharge area for the Town's primary drinking water supply.

Also enclosed are aerial photographs that illustrate the close proximity of an unused auto-unloading facility located along the same rail line but not within the Zone II aquifer area

The Town's recommendation is that the STB require the railroad to utilize the existing facility The Town also requests the railroad allow installation of the monitoring wells as depicted in the attached plans of Geolnsight, Inc

Thank you.

Sincerely,

Shaun A Suhoski

Town Administrator

cc.

Board of Selectmen Conservation Commission Water Dept Foreman

Board of Health

## CONCINNS with

#### Pan Am Sowihern Proposed Auto Unloading Facility

August 25th, 2008

\_

# PAS and the Valley Shared by Aver, Littleton and Westford



#### Background

Transportation Industries) and Norfolk Southern to The proposal to merge PanAm (formerly Guilford am auto uniloading facility in Ayer to accommodate 310 form PanAm Southern (PAS) includes a plan to build


(Concerns about the unloading facility at this location:

— On aquiffer for Ayer and Liftileton's Water Suppply

- Surrounded by wetlands
- Home to endangered species turtiles and salamanders
- Aliternate facility exists and is currently not in use
- Guilliburd owns an auto unipading site in Ayer that is leased to CSX until

## Saving Our Aquifer

"Suddenty it is so clear: the world is pollwing, diverting and depleting the running out of fresh water. Humanity is every passing day, our demand for fresh from Blue Gold by Barlow and Clarke. Abousands more people are put at risk. water outpaces its availability and wellspring of life at a startling rate. With



#### Well Sites



-

# Spectacle Pond Wells


- Major source of water for towns of Ayer & Littleton
- Collective capacity of 3.5 million gallons per day for the 3 wells for Alyer and Littileton
- NO new sources of sufficient, adequate water can be developed within the town of Ayer
- Only prixime water supply for Ayer
- 0 Source of water for our industries which rely beavily on it for their **Manupond**
- Catins, Nasoya, Aquatina, Pepst, Nashoba Hospital
- Paving large tracks of land reduces both the quality and quantity of water a Burgapan

# Unloading Site Locations



### impervious Surfaces Diminish Watter Quantity and Quallity

- At even low level of imperviousness (10%)
- Increased runofff
- Reduced water quality
- Shrinks biodiversity
- Diminishes aquifer volume
- Raim water lost through evaporation
- And what if there is a spill?



# Special Features of this Area

- 28° with an average depth of  $6^{\circ} 8^{\circ}$ Depth of groundwater ranges between 3.66° to
- Soil is mainly sand and gravel
   Limited vegetation
- which is difficult to clean up Arrea down gradient from the site contains wetlands and thick, moist dark anaerobic peat
- Raimwater is immediately absorbed no puddles

# Accidental Fuel Spills Can Occur

- · Fuel spill can occur from
- Train locomotive
- 18- wheel mucks
- New cars
- Used employee cars
- Hydraulic lifts

## Fuel Spills Do Occur

- 5/30/2008 Diesel fuel spill at Willow Rd. Crossing. Notified by the Railpond. HaziMat clean up. The spill was a minor spill under 10 gallons and cleaned up by Rail Road . . .
- 7/08/2007 Diesel suel spill in Hill Rail Yard from leaking suel line on train. combinued to leak causing two areas of diesel contamination Could have been as much as 100 gallons. Train was moved to Devens where it
- day after the leak by concerned worker. Could have been as much as 1700 ... 8/09/2006 — Diesel fluel spill in Hill Rail Yard from leaking train. Notified the
- 09/01/2003 Imvestigated a modified trash barrel containing empty bags ofpoison on raill road property off Willow Rd.
- commolled by District 6 Haz Mat Team. 10/18/2001 - Leaking Methanol tank car in Hill Rail Yard- Major incident
- 0 10/15/98-Diesel fuel leak approximately 10-12 gallons. Hill Rail Yard


#### Spill Locations



#### Risk

- Cleanup cost is extreme
- Remove the contaminant
- Provide alitemate water sources for towns and industries Industries that rely on water for their products will
- be forced to shut down
- Hospital/nursing home patients will be put at risk

### 3landing's Turtles



- Endangered species
- Local sightings registered with the National Heritage Endangered Species Program
- Other sightings spotted turtle, blue spotted salamander

### Recommendation

oWe recommend that the PAS proposal to build a new unloading facility on the San Vel site be rejected environmentally sensitive site is not appropriate the street and NOT in zone III -Am alternate site already exists that is directly across for this kind of development

#### Well Sites



# Unloading Site Locations



LEGEND

NOTES -

TOWN OF AYER

TO

